

ANNEXURE A – SITE PHOTOGRAPHS



Condition of the slipway from the road-side.



Condition of the slipway.



Bottom of the slipway during low tide as seen towards the north.



Bottom of the slipway during low tide as seen towards the south.



Vegetation debris at the bottom of the slipway.



Condition of the slipway.



The northern end of the jetty showing the completed layers of the .



Weinstalled mooring poles.



Established *Zostera* along the base.



Successfully installed mooring poles.



Revegetated reno-matresses.



Revegetated reno-matresses.



Completed jetty showing the gang-plank, jetty and fingers as seen towards the south.



Successfully completed and operational jetty as seen towards the south.



Revegetated reno-matresses.



Revegetated reno-matresses.



The 5m gap in between the mooring fingers.



Successfully completed and operational jetty as seen towards the south..



Attached floating jetty and mooring finger.



The southern end of the San Marino jetty and the northern end of the Blue Waters River Estate jetty.



Condition of the jetty and the reno-matresses on low tide as seen towards the north.



Attached floating jetty and the 4-meter-long by 0.7-meter-wide mooring finger.



Attached floating jetty and mooring fingers with the 5m gap as seen towards the north.



Condition of the jetty showing the gang-planks on low tide as seen towards the north.



Reno-mattress toe at the bottom of the riverbank.



Rehabilitation of the riverbank.




Rehabilitation of the riverbank.



Rehabilitation of the riverbank.



Tie-in point with Blue Waters.



Reno-mattress toe at the bottom of the riverbank.