

APPENDIX A – SITE PHOTOGRAPHS



Access to the site off Darwin Road as seen towards the site. Some sand from the site is evident at the time.



The previous temporary stormwater pond has been decommissioned and filled in.



The previous temporary stormwater pond has been decommissioned and filled in.



The previous temporary stormwater pond has been decommissioned and filled in.



Construction and enlargement of Channel 1 along the existing outlet channel of the temporary pond.



Darwin road reserve extension as seen towards the southeast.



Roadside channels within the road reserve of Darwin Road.



Roadside channels within the road reserve of Darwin Road.



Construction and enlargement of Channel 1 along the existing outlet channel of the temporary pond.



Central channel cunettes constructed along the enlarged Channel 1 to assist in low-flow conveyance and drainage.



The stormwater culvert currently serving as an overflow diversion towards the decommissioned temporary pond.



Roadside stormwater culvert channels within the road reserve of Darwin Road.



Central channel cunettes constructed along the enlarged Channel 1 to assist in low-flow conveyance and drainage.



Culvert headwall along Channel 1 underneath Brass Avenue gravel access road.



Brass Avenue gravel access road as seen towards the southeast.



Brass Avenue gravel access road as seen towards the west.



From Brass Avenue gravel road as seen towards the southeast towards the Mosselbank River.



Channel 2 towards the box culvert inlet to the new wet pond forebay as seen towards the east.



New box culvert inlet to the new dry pond forebay as seen towards the east.



The new dry stormwater pond as seen from the west towards the east.



The new dry pond forebay.



The new dry pond forebay.



The new dry pond forebay.



The new dry stormwater pond.



Along the southern boundary of the new pond, showing the composted banks.



The permanent pool of the regional pond being irrigated, seeded with Bermuda grass.



The condition of the temporary stockpile area as seen immediately south of the new pond towards the south.



The condition of the temporary stockpile area as seen immediately south of the new pond towards the south.



Composted and rehabilitated temporary access road.



Along the southern boundary of the new pond, showing the composted banks.



The permanent pool of the regional pond being irrigated, seeded with Bermuda grass.



Condition of the wetland area of the Mosselbank River.



Condition of the wetland area of the Mosselbank River.



Eastern embankment of the dry regional pond adjacent to the wetland area of the Mosselbank River.



Gabion spillway drop structure with stilling basin as seen towards the east.



Outlet structure with weir openings and flapgate.



Outlet structure with weir openings and flapgate.




The permanent pool of the regional pond being irrigated, seeded with Bermuda grass.




Gabion spillway drop structure with stilling basin.



Gabion spillway drop structure with stilling basin as seen towards the south.



Condition of the embankment along Brass Avenue gravel road.



Forebay access ramp.