

APPENDIX A – SITE PHOTOGRAPHS




Condition of the first few constructed units off Hyacinth Lane.



Construction area is screened at the entrance of the site along Soapberry Close and Nature Boulevard.



Construction area is screened at the entrance of the site along Soapberry Close and Nature Boulevard.



Site induction covers safety, environmental rules, and work protocols.



Condition of the first few constructed units off Hyacinth Lane.



Permeable paving "grass block", SUDS intervention.



Screened construction area off Hyacinth Lane.



Permeable paving "grass block", SUDS intervention.



Screening held in place with sandbags.



Demarcation in place surrounding the landscaping area and surrounding construction area.



Demarcation in place around the construction of the apartment blocks.



Demarcation in place around the construction of the apartment blocks.



Demarcation netting is installed to prevent contractor falls at edges.



SUDS being installed.



Construction of the apartment units.



Active cement batching in cement dams.



Landscaping of outside gardens in progress.



Curbs being installed.



Edge of bush/natural buffer area that will undergo riparian rehabilitation.



No-go demarcation in place along the entire Malgas River boundary.



Security fence installed along with sewage service that has been tied into the municipal network.



Gabion mattresses installed to prevent uncontrolled surface flow.



Gabion mattresses installed to prevent uncontrolled surface flow.



Edge of bush/natural buffer area that will undergo riparian rehabilitation.



Civil services along the apartment block being installed.



Temporary stormwater channels for surface flow.



Temporary stormwater channels for surface flow with hay bales.



Installed hay bales along the security fence.



Topsoil temporary swale for stormwater diversion and will be used for rehabilitation.



Demarcation surrounding the stormwater outline.



Stormwater outlet towards the riparian area.



Demarcation surrounding the stormwater outline.



Stormwater outlet towards the riparian area.



Construction area and temporary laydown area of construction material.



Clubhouse pool and associated infrastructure being constructed.



Electrical lines being installed.



Indigenous plants being planted in the rehabilitation zone.



Indigenous plants being planted in the rehabilitation zone.



Indigenous plants being planted in the rehabilitation zone.



Indigenous plants being planted in the rehabilitation zone.



Bin in place near the no-go area.



Chemical toilets in place along the construction areas.



Newly installed hay bale along the riparian zone and security fence.



Contractors busy installing the gabion base along the low-lying sections of the buffer area.



Decomposed hay bale still in place.



Contractors busy installing the gabion base along the low-lying sections of the buffer area.



Temporary construction laydown area.



Construction vehicles being serviced.



Cement batching in progress without the necessary mortarboards or drip trays.



Cement spills adjacent to the rehabilitation area and stormwater outlet.



Water truck available for dust suppression.



Construction site camp.



Topsoil and subsoil stockpiles were excavated after roadways were cleared.



Sewage material along Nature Boulevard.



Installed hay bales and gabion mattresses towards the corner of the property.



Installed hay bales and gabion mattresses towards the corner of the property.



Temporary access road off plantation road.



Indigenous trees are to be planted for rehabilitation.



Construction site camp with build in toilets feeding into the sewage network on-site.



Construction laydown area where civil services are being installed.



Lockable storage containers within the site camp.



Jojo tanks are to be installed at each unit.



Lockable storage containers within the site camp.



Appropriate signage in place indicating flammable content.



On-site nursery containing the search and rescue plants behind the site camp.



On-site nursery containing the search and rescue plants behind the site camp.



Fire bucket to extinguish cigarette buds.



Fire extinguishers available at the site camp.



Civil services being installed along with the roads being paved.



Laydown area adjacent to the site camp.



Drip tray in place below the fuel bowser.



Cement conveyor belt, demarcation around the area.



Electrical installations in progress at the individual units.




Screening around the construction area in place.


Environmental File




Environmental Management Plan




Stormwater Management Plan




Run-off coefficient




Plant species list




Invasive Alien Control Plan.




Original EA



Amendment EA



Induction register



Subcontractors list



Policies and Emergency Procedures.