

ANNEXURE A – SITE PHOTOGRAPHS



The access road leading from the northeast towards the site with the shrubs towards the right of picture.



Syzygium shrubs as hedging and screening with drip irrigation installed along the northern boundary.



Syzygium shrubs as hedging and screening with drip irrigation installed along the northern boundary.




Syzygium shrubs as hedging and screening with drip irrigation installed along the northern boundary.



Stormwater catchpit along the northern boundary of the site between the footprint and the houses.



Stormwater catchpit along the northern boundary of the site between the footprint and the houses.




The access road leading around the site boundary along the east of the site seen towards the south.



Along the eastern boundary of the site seen towards the northwest across the site.



Eastern boundary of the development footprint at the entrance gate to the site.



From the entrance gate to the site seen towards the west and the control station.



Completed electrical control stations.



Completed electrical control stations.



Completed electrical control stations.



Completed electrical control stations.



Solar panels as seen from the centre of the site towards the south.



Solar panels and condition of completed works as seen from the northeastern corner towards the southwest.



Condition of the completed panel structures as seen towards the west.



Condition of the completed panel structures along the eastern boundary as seen towards the south.



Condition of the completed panel structures as seen from the eastern boundary towards the west.



The access road along the southern boundary as seen towards the west.



Adjacent to the site camp area, some remaining building sand and aggregate for mixing concrete is still in place.



Along the northern boundary of the site as seen towards the west where stormwater measure were completed.



Condition of a completed stormwater catchpit along the northern boundary of the site.



Completed stormwater catchpit along the northern boundary of the site as seen towards the south.



Along the northwestern boundary of the site as seen towards the east.



Along the northwestern boundary of the site as seen towards the west.



Along the inside of the northern fence as seen towards the west.



From the northwestern boundary of the site footprint as seen towards the east.



From the northwestern boundary of the site footprint as seen towards the south.



The ring main unit located immediately northwest of the site.



The ring main unit located immediately northwest of the site.



From the ring main unit as seen towards the east along the northern boundary access road.



The dam sludge which was placed along the gravel road towards the west of the site.



Along the western boundary of the site within the staked buffer area as seen towards the south.



Along the western boundary of the site within the staked buffer area as seen towards the south.



Along the western boundary of the site within the staked buffer area as seen towards the north.



Along the western boundary of the site within the staked buffer area as seen towards the south.



Along the western boundary of the site where the water pipeline connects to the internal water pipeline.



Along the western boundary of the site where the water pipeline connects to the internal water pipeline.



The location of the water pipeline within the no-go area has been overgrown again with indigenous veld.



The buffer area no-go stakes still in place along the west of the site as seen towards the north.



The access road along the southern boundary of the site as seen towards the east.