

APPENDIX A – SITE PHOTOGRAPHS




Site camp area with storage trailer, construction materials, and temporary shelter structure.



Construction waste stored in a trailer at the site camp, secured in plastic sheeting to prevent windblown litter.



Concrete cutting saw stored at the site camp.



Lockable storage containers located within the site camp with appropriate warning signage.



Asphalt paver located within the site camp.



Toilets in place adjacent to the site camp.



Toilets in place adjacent to the site camp. Vegetation debris surrounding the area.



Workers' homesteads to be demolished and crushed; Firwoods Homestead to be retained.



Workers' homesteads to be demolished and crushed; Firwoods Homestead to be retained.



Existing Firwoods Homestead to be retained.



Access road off New Eskdale Street chipped and sprayed.



Vineyards cleared due to unproductive vines.



Stormwater pipeline material adjacent to the road being chipped and sprayed west of the Firwoods Homestead.



Topsoil stockpiles towards the southwest.



Towards the west, internal roads are being chipped and sprayed with material placed along the development.



Towards the west, internal roads are being chipped and sprayed with material placed along the development.



Road surfaces being prepared for asphalt.



Road surfaces being prepared for asphalt



1.1m stormwater pipeline material adjacent to the large stormwater pond to be installed.



Large stormwater pond located east of the existing Firwoods Homestead.



Condition of the large stormwater pond located east of the existing Firwoods Homestead.



Condition of the large stormwater pond located east of the existing Firwoods Homestead.



Stormwater pipeline installed in the large pond to direct water toward the main outlet along the Berg River.



Demolished buildings crushed on-site for reuse as G7 material in road construction.



Stormwater pipeline installed in the large pond to direct water toward the main outlet along the Berg River.



Vineyards cleared due to unproductive vines.



Vineyards to be cleared due to unproductive vines.



View of the site towards the site camp looking northwest.



Cleared vines have been placed adjacent to the Homestead and stormwater pond.



Cleared area adjacent to the Homestead and stormwater pond wet due to the recent rain.



Topsoil stockpiles southwest of the large stormwater pond.



View of the existing Firwoods Homestead and stockpile laydown area towards the southwest.



Cleared area towards the east designated for agriculture along the Berg River.



Cleared area towards the east designated for agriculture along the Berg River.



Cleared area towards the west where vineyards have been cleared.



Cleared area towards the east designated for agriculture along the Berg River.



Smaller stormwater pond towards the north.



Smaller stormwater pond towards the north.



Excavated stormwater outlet channel north towards the Berg River.



Excavated stormwater outlet channel north towards the Berg River.



Excavated stormwater outlet channel north towards the Berg River.



Condition of the Berg Riverbank north of the development site.



Dumped base material after the construction of the mall west of the development site, creating a quarry.



Dumped base material after the construction of the mall west of the development site, being reused.



Workers' house still to be demolished and crushed.



Cleared eastern area where unproductive vineyards were removed, to be reinstated with new vines.



Civil service installations adjacent to the site camp.



Stockpile material adjacent to the site camp towards the southwest.



Chemical Toilet in place within the site camp.



Bin and wire structure available within the site camp for waste disposal.



Wire structure available within the site camp for waste disposal.



Civil services, kerbs, and road surface being prepared west of the site camp at the entrance to the site.



Civil services, kerbs, and road surface being prepared west of the site camp at the entrance to the site.



Civil services, kerbs, and road surface being prepared west of the site camp at the entrance to the site.



Internal road network being cut, shaped, and prepared.



Revegetated topsoil stockpiles adjacent to the site camp.



Water truck available for dust fallout on site.



Asphalt material stockpiles adjacent to the site camp where roads are being chipped and sprayed.



Topsoil and material stockpiles separated adjacent to the site camp.



Asphalt mixing with a mortar board in place.



Civil services, kerbs, and road surface being prepared west of the site camp at the entrance to the site.



Condition of New Eskdale Street towards the southwest where the ClearVu boundary fence is being installed.



Condition of New Eskdale Street towards the southwest, where the ClearVu boundary fence is being installed.



Firwoods Homestead Beacon along New Eskdale Street.



Internal road surfaces being chipped and sprayed. Entrance to the site towards the Firwoods Homestead.



Fibre installations along New Eskdale Street.



Condition of New Eskdale Street towards the North.



Condition of New Eskdale Street towards the North. Civil services being installed along the road.



Cleared southern area where unproductive vineyards were removed, to be reinstated with new vines.



Stockpile area towards the southwest where roads are being excavated.



Topsoil stockpiles towards the southwest, adjacent to the foreman's house.



Roads being chipped and sprayed south of the foreman's house.



Ready mix cement for kerb installations.



Roads being chipped and sprayed south of the foreman's house.



Roads being excavated and cut south of the foreman's house.



Stockpile area southwest of the site. Topsoil stockpiles have been revegetated.



Roads being excavated and cut south of the foreman's house.



Stockpile area southwest of the site. Topsoil stockpiles have been revegetated.



Excavated stormwater channel towards the southwest.



Collapsed stormwater channel with a new, formalised channel under construction.



Collapsed culvert to be upgraded.



Recent rain filled the excavated stormwater channel; sandbags were placed to control flow.



Stormwater channel being upgraded towards the southwest.



Stormwater channel being upgraded towards the southwest.



Fibre being installed along New Eskdale Street.




ClearVu boundary fence being installed along the western boundary of the site.


Environmental File




Environmental file available at the site office.




Method Statement for Traffic Management.




Method Statement for Cement Handling.



ECO reports submitted.




Notification of the 2022 Environmental Authorisation.




2022 Environmental Authorisation.




EMP included in contract documents.




Environmental Management Programme.




Environmental induction register.




Project team and farmer have been made aware of the communication received from the Golfklub.




Correspondence from the Golfklub regarding waste removal.



Correspondence from the EAP and contractor regarding the raised concern.



Correspondence from the EAP and contractor regarding the raised concern.



Chemical toilet hire invoice.