

APPENDIX A – SITE PHOTOGRAPHS

Site 28(1).1



Completed upgraded/replaced SW outlet structure.



Chemical toilet available adjacent to the works area.



Completed upgraded/replaced SW outlet structure.



Completed reconstruction of stormwater outlet structure headwall.



Backfilling and shaping of area adjacent to the works completed.



Backfilling and shaping of area adjacent to the works completed.



New gabion/mattress flood attenuation works completed. Local residents responsible for dumping.



New gabion/mattress flood attenuation works completed. Local residents responsible for dumping.



Backfilling and shaping of area adjacent to the works completed.



Backfilling and shaping of area adjacent to the works completed.



Backfilling and shaping of area adjacent to the works completed.



New gabion/mattress flood attenuation works completed. Local residents responsible for dumping.



Completed reconstruction of gabion retaining wall. Local residents responsible for dumping.



Completed reconstruction of gabion retaining wall. Local residents responsible for dumping.



Completed reconstruction of gabion retaining wall. Local residents responsible for dumping.



Completed reconstruction of gabion retaining wall.



Completed reconstruction of gabion retaining wall. Local residents responsible for dumping.



Completed reconstruction of gabion retaining wall. Local residents responsible for dumping.



Shaping and tie in at the ends of the gabion structure completed. Local residents responsible for dumping.



Completed reconstruction of gabion retaining wall. Local residents responsible for dumping.



Residential area adjacent to the Municipal sewage pump station.



Completed reconstruction of gabion retaining wall. Slope below the retaining wall has been shaped.



Shaping and tie in at the ends of the gabion structure completed. Local residents responsible for dumping.



Backfilling completed with rehabilitation (topsoil and grass seed/sods) finalised.



Newly constructed stormwater inlet infrastructure.



Newly constructed manhole infrastructure.




Slopes adjacent to the drainage channels have been shaped and rehabilitated, erosion backfilled.



Slopes adjacent to the drainage channels have been shaped and rehabilitated, erosion backfilled.



Completed armorflex stormwater channel and mitre drains.



Slopes adjacent to the drainage channels have been shaped and rehabilitated, erosion backfilled.



Slopes adjacent to the drainage channels have been shaped and rehabilitated, erosion backfilled.



Newly construction stormwater outlet infrastructure.



Completed armorflex stormwater channel, inlet and manhole infrastructure.



Completed armorflex stormwater channel.



Completed armorflex stormwater channel.



New terramesh and gabions constructed for main drainage channel



Completed armorflex stormwater channel.



Completed armorflex stormwater channel and mitre drains.



New terramesh and gabions constructed for main drainage channel



New terramesh and gabions constructed for main drainage channel.



New terramesh and gabions constructed for main drainage channel.



Replaced stormwater inlet infrastructure.



Backfilling and shaping of area adjacent to the works completed.



New gabion/mattress flood attenuation works completed.




Backfilling and shaping of area adjacent to the works completed.



New gabion/mattress flood attenuation works completed.



New gabion/mattress flood attenuation works completed.



New gabion/mattress flood attenuation works completed.



New gabion/mattress flood attenuation works completed.



Backfilling and shaping of area adjacent to the works completed.



New gabion/mattress flood attenuation works completed.
Local residents responsible for dumping.



Backfilling and shaping of area adjacent to the works completed.

Site 28(1).69 (a & b)



New gabion/mattress flood attenuation works completed. Local residents responsible for dumping.



Backfilling and shaping of area adjacent to the works completed.



Backfilling and shaping of area adjacent to the works completed.



New gabion/mattress flood attenuation works completed. Local residents responsible for dumping.



New gabion/mattress flood attenuation works completed. Local residents responsible for dumping.



New gabion/mattress flood attenuation works completed. Local residents responsible for dumping.



New gabion/mattress flood attenuation works outlet completed. Local residents responsible for dumping.



Local residents responsible for dumping.



Local residents responsible for dumping.



New gabion/mattress flood attenuation works outlet completed. Erosion damage fix and rehabilitated.



New gabion/mattress flood attenuation works outlet completed. Local residents responsible for dumping.



Local residents responsible for dumping.



Access road towards the construction area.



Replaced stormwater and manhole infrastructure.



Replaced stormwater and manhole infrastructure.



Replaced stormwater and manhole infrastructure.



Access road adjacent to the works area.



Upgraded stormwater outlet infrastructure.



New gabion/mattress flood attenuation works outlet completed.



Upgraded stormwater outlet infrastructure.



Upgraded stormwater outlet infrastructure. Erosion damage to be fixed and rehabilitated.



Upgraded stormwater outlet infrastructure. Erosion damage to be fixed and rehabilitated.