

APPENDIX A – SITE PHOTOGRAPHS



The intersection of Klipheuwel Road (R304) and Protea Road.



At the western end of Protea Road where stormwater culverts are installed adjacent to the road shoulder.



At the western end of Protea Road where stormwater culverts are installed adjacent to the road shoulder



Newly upgraded stormwater culvert.



Installed stormwater side drains.




Installed stormwater side drains.



Installed stormwater side drains and inlet structure.



Condition of Protea Road, successfully resurfaced.



Stinkwort (*Dittrichia graveolens*) observed establishing along the road reserve, requiring ongoing management.



Stinkwort (*Dittrichia graveolens*) observed establishing along the road reserve, requiring ongoing management.



Condition of Protea Road, successfully resurfaced.



Stormwater outlet structure successfully installed.



Installed gabion retention wall along the previous cuttings along the Protea Road.



Installed gabion retention wall along the previous cuttings along the Protea Road.



Reinstated fencing along the development route.



Golden Wreath Wattle observed establishing along the road reserve, requiring ongoing management.



Installed stormwater side drains.



Condition of Protea Road, successfully resurfaced.



Gabion mattress installed.



Stormwater outlet structure successfully installed.



Stormwater inlet structure successfully installed.



Stormwater side drains installed along the road reserve.



Stormwater side drains installed along the road reserve as seen towards the west.



Rehabilitation of the road reserve in progress.



English oak trees trimmed along the road reserve towards the west near the Joostenberg Primary School.



Upgraded stormwater inlet structure.



Upgraded stormwater outlet structure with installed gabion mattresses.



Excavated stormwater side drain channels successfully installed with gabion retaining walls.



Recently constructed concrete-lined roadside stormwater drainage channel and slope stabilisation.



Hessian sausage erosion controls installed for roadside slope rehabilitation.



Hessian sausage erosion controls installed for roadside slope rehabilitation.



Revegetation established along rehabilitated roadside embankment slopes.



Revegetation established along rehabilitated roadside embankment slopes.



Hessian sausage erosion controls installed for roadside slope rehabilitation.



Hessian sausage erosion controls installed for roadside slope rehabilitation.



Golden Wreath Wattle observed establishing along the road reserve and stormwater channel.



Golden Wreath Wattle observed establishing along the road reserve and stormwater channel.



Stinkwort (*Dittrichia graveolens*) observed establishing along the road reserve, requiring ongoing management.



Condition of Protea Road, successfully resurfaced eastern end at the start of the contract.



Condition of Protea Road, successfully resurfaced eastern end at the start of the contract.



Condition of Protea Road, successfully resurfaced eastern end at the start of the contract.



Condition of Protea Road, successfully resurfaced eastern end at the start of the contract.