

Hilland Environmental

Environmental Assessment Practitioners

166 Mount View, Victoria Heights
P.O. Box 590, GEORGE, 6530
Western Cape, South Africa

Tel: +27(0)44 889 0229
Fax: +27 (0) 86 542 5248
Mobile: + 27 (0) 82 5586 589
E-mail: info@hilland.co.za
www.hilland.co.za

MOS24/1136/33
15 March 2024

Dear Willie Uys,
Alicente 174 BK
willie.uys@cybersouth.co.za

BY Email

RE: NON-COMPLIANCE PENALTY IN TERMS OF THE ENVIRONMENTAL MANAGEMENT PROGRAMME FOR FAILURE TO INSTALL NO-GO DEMARCATION – ERF 4716, GROOT BRAK RIVIER

The letter serves to notify the contractor, Alicente 174 BK, represented by Mr Willie Uys, of the non-compliance in terms of the Environmental Management Programme (EMPr) for failure to install the No-Go demarcation and silt protection for the northern development section (garage site).


The contractor was requested to install the No-Go demarcation for the garage site on May 2023, written request on the WhatsApp group on 1st March 2024 and second verbal request on 12th March 2024. During our follow-up inspection on 14th March 2024, the No-Go demarcation had still not been installed for the garage site and as result thereof, workers are walking through the No-Go zone where the Milkwood trees were transplanted to.

The contractor is hereby instructed to install the No-Go demarcation for the garage site by no later than 16 March 2024 and submit photographic proof thereof to the ECO.

Damage to and protection of the transplanted milkwood trees – the trees transplanted have been damaged through construction activities and failure to demarcate and protected the trees. Thank you for now demarcating the trees, however access through the No-Go area is still disturbing these trees, they need to be watered daily. In order to try revive these trees please include compost around the trees and an application of Bounce back or similar product.



14 March 2024



Shade netting to be installed around the working area as required.

Failure to comply with the EMPr results in a penalty being imposed on the contractor in terms of Section 12.4 of the EMPr. Instead of monetary fine, the following **fine is imposed for Non-compliance** with the No-Go demarcation for the garage site:

- The contractor must buy either three (3) X 20 Liters or five (5) X 4 Liters additional Milkwood trees (*Sideroxylon inerme*) and plant as indicated by the ECO.
- The rescued and new trees must be looked after (compost, food and water) for the remainder of the construction phase.

If you require any further information or assistance, please contact us on (044) 889 0229 (Tel) 086 542 5248 (fax) or Email: environmental2@hilland.co.za / cathy@hilland.co.za.

Kind Regards

Inge Delport
for Hilland Environmental

Copy to: Mr Willie Nel - nelw@pminc.co.za