

ANNEXURE A – SITE PHOTOGRAPHS



The intersection of Gcubane Road with Sheffield Road as seen towards the west toward Sheffield road.



Existing construction access off Gcubane Road with the required safety and construction signage on the gates.



Entrance to the site securely closed off to the public during construction.



Stormwater manholes installed towards the northern boundary of the site.



Newly surfaced internal road within the development where a service manhole can also be seen.



Kerbs being installed within the development footprint. A mixing board in place for the kerb mix.



Building rubble temporarily stockpiled near the construction entrance.



Condition of the recently surfaced internal road along the Sheffield road boundary with service manholes.



Kerbs being installed near the northern boundary and the temporary construction access.



View of the contractors site offices and storage containers areas within the future public space area.



Chemical toilet in place adjacent the current works and secured to the ground.



Material laydown area sufficiently demarcated with orange netting in place.



Temporary laydown area immediately east of the contractors camp with temporary fencing.



Waste skips in place at the laydown area. Proof of disposal slips are available in the environmental file.



Temporary material laydown area, with material fenced in.



Empty bitumen drums and flowbins for water storage in place at the material laydown area.



The contractors site offices located in the centre of the development footprint at the future public open space.



The contractors site offices located in the centre of the development footprint at the future public open space.



Contractors camp and eating area also serving as the emergency assembly point.



Condition of the contractors camp showing several additional storage containers.



Material laydown areas neatly stored within the contractors camp.



Excavated soils and builders rubble stockpiles behind the material laydown area.



Condition of the site along the eastern boundary of the site as seen towards the south.



Condition of the newly surfaced road along the eastern boundary seen towards the south.



The newly surfaced road at the southeastern corner of the site connecting to Ngqwangi Drive.



From the southwestern boundary of the site as seen towards the west.



Along the south boundary of the site, as seen towards the west.



Along the south boundary of the site, as seen across the site towards the northwestern corner of the site.



Condition of the civil services connection points completed along the internal roads.



From the internal road as seen towards the southwest in the direction of the stormwater detention pond.



Current condition of the stormwater detention pond with some bullrush and acacia shrubs.



Current condition of the stormwater detention pond with some bullrush and acacia shrubs.



Current condition of the stormwater detention pond with demarcation stakes in place along the eastern bank.



Current condition of the stormwater detention pond with stakes in place.



The stormwater detention pond along the internal road leading immediately north as seen towards the west.



Excavated soils and builders rubble stockpiles west of the contractors camp on site.



The condition of the northwestern section of the site, as seen towards the northwestern corner.




Condition of the completed internal road and kerbs as seen towards Sheffield Road in back of picture.


Environmental File On-Site




Environmental file available at the site office.




Attendance register.




Environmental induction register.




Environmental induction register.




Environmental induction register.




EMPr available within the environmental file.




Location of spoil site confirmed.




List of Method Statements available.




Material safety data sheet for gasoline.




Material safety data sheet for diesel.




Confirmation of chemical toilet hire.



Proof of Waste disposal slips.



Proof of Waste disposal slips.



Formal ECO reports