

APPENDIX A – SITE PHOTOGRAPHS



Landscaping with indigenous vegetation at the entrance of the site.



Screening surrounding the development area. Screening of the completed residents.



Cleared area for residential units mulched with woodchips.



Condition of the first completed residential phase.



Landscaping with indigenous vegetation surrounding the residential units.



Condition of the first completed residential phase with screening in place.



Landscaping with indigenous vegetation surrounding the residential units.



Cleared area for residential units mulched with woodchips.



Condition of the first completed residential phase.



Condition of the first completed residential phase.



Cleared area for the next phase of development where services are being installed.



Cleared area for the next phase of development. Paving and curb installations in progress.



Cleared area for the next phase of development where services are being installed.



Cleared area for the next phase of development. Paving and curb installations in progress.



Condition of rehabilitated cleared sites where services were installed.



Location of the proposed swales adjacent to the internal road.



Central stormwater channel.



Existing residential house on-site.



Natural area where the next phases of the development are to commence.



Natural area where the next phases of the development are to commence.



Small seasonal dam on site due to the recent rainfall.



Natural vegetation on site, along with the stockpiled subsoil and topsoil after site clearance.



On-site dam to be reconstructed into a retention pond.



On-site dam to be reconstructed into a retention pond.



Cleared section of the site for road access.



Successfully installed sewage pipeline towards the Modderrug River.



Successfully installed sewage pipeline towards the Modderrug River.



Modderrug River buffer zone.



Successfully installed sewage pipeline towards the Modderrug River.



Stockpiled subsoil and topsoil after site clearance.



Cleared section of the site for road access.



Cleared section of the site for road access.



Sewage systems being installed towards the entrance of the site.



Chemical toilet in place adjacent to the works area.



Lockable storage container in place near the next phase of the development, where services are being installed.



Existing residence on-site.