

APPENDIX A – SITE PHOTOGRAPHS



Entrance to the site camp of the R102. Coordinates: 34° 6'10.47"S; 22° 6'51.90"E.



Entrance to the site camp of the R102. Coordinates: 34° 6'10.47"S; 22° 6'51.90"E.



Construction machinery making use of existing hall roads.



Site camp establishment within the previous Swans Nursery footprint.



Fuel bowser available at the site camp on an impermeable surface.



Condition of the Vegetation on the Former Swans Nursery Site



Condition of the Vegetation on the Former Swans Nursery Site



Storage containers located within the newly established site camp.



Indigenous trees planted within the former Swans Nursery for use in site rehabilitation.



Indigenous trees planted within the former Swans Nursery for use in site rehabilitation.



Remaining topsoil stockpiles at the site camp for rehabilitation.



Remaining topsoil stockpiles at the site camp for rehabilitation.



Remaining rescued aloes at the site camp for rehabilitation.



Previous site camp location within RE/219.



Previous site camp location within RE/219.



Previous site camp location within RE/219. Borderline shown to the West.



Retaining wall constructed along RE/219 boundary following unlawful clearing.



R102 being upgraded as per the municipal planning conditions for the construction of the Garden Walk Mall.



R102 being upgraded as per the municipal planning conditions for the construction of the Garden Walk Mall.



R102 being upgraded as per the municipal planning conditions for the construction of the Garden Walk Mall.



R102 being upgraded as per the municipal planning conditions for the construction of the Garden Walk Mall.



Stormwater services being installed along the entrance of the Garden Walk Mall along Monte Christo Rd.



Entrance of the Garden Walk Mall along Monte Christo Rd.



Storage containers are along the retention berm on the eastern boundary.



Service yard and delivery area constructed for retail tenant logistics.



Service yard and delivery area constructed for retail tenant logistics.



Storage and laydown area along the RE/219 boundary and retention wall being rehabilitated.



Storage and laydown area along the RE/219 boundary and retention wall being rehabilitated.



Storage and laydown area along the RE/219 boundary and retention wall being rehabilitated.



Chemical toilets located within the Service yard and delivery area along the eastern and RE/219 boundary.



Service yard and delivery area constructed for retail tenant logistics.



Storage and laydown area along the RE/219 boundary and retention wall being rehabilitated.



Storage and laydown area along the RE/219 boundary and retention wall being rehabilitated.



Storage and laydown area along the RE/219 boundary and retention wall being rehabilitated.



Rehabilitation Phase 3 in progress along the RE/219 boundary, on top of the retention wall.



Rehabilitation Phase 3 in progress along the RE/219 boundary, on top of the retention wall.



Rehabilitation Phase 1 in progress along the RE/219 boundary, on top of the retention wall.



Construction boundary along the R102.



Construction boundary along the R102.



Final construction in progress along the R102.



Installing paving blocks as part of a hard-surfaced area.



Installing paving blocks as part of a hard-surfaced area.



Installing paving blocks as part of a hard-surfaced area.



View of the parking area of the Garden Walk Mall.



Building sand stockpile and bin in place near paving works within the parking area.



Installing paving blocks as part of a hard-surfaced area.



Landscaping of the parking area of the Garden Walk Mall.



Landscaping of the parking area of the Garden Walk Mall.



View of the parking area of the Garden Walk Mall.



Skip in place near paving and cement works.



Bin in place near paving and cement works.



Paving and cement works in progress.



Paving and cement works in progress.



Paving and cement works in progress.



Paving and cement works in progress.



Skip in place near paving and cement works.



Building sand stockpile adjacent to ongoing paving and masonry activities.



Preparing mortar on-site for ongoing paving or masonry activities.



Painting works in progress on the exterior façade of the mall.



Emergency contact information available within the construction area of the mall.



Waste removal truck collecting skips from the construction site.



Skips available along the parking area of the Garden Walk Mall construction area.



Chemical toilets available along the parking area of the Garden Walk Mall construction area.



Chemical toilets available along the parking area of the Garden Walk Mall construction area.



Ground preparation and material handling for paving and drainage works.



Ground preparation and material handling for paving and drainage works.



Empty cement bags collected for disposal.



Construction of the entrance of the mall, paving, and cement works in progress.



Skip available along the parking area of the construction area.



Laydown area adjacent to Burger King.



Chemical toilets available along the parking area of the construction area.



Construction of the entrance of the mall, paving, and cement works in progress.



Completed stormwater services adjacent to the entrance of the site.



Landscaped retaining wall along the entrance of the site.



Stormwater services adjacent to the entrance of the site being installed.



Stormwater services adjacent to the entrance of the site being installed.



Landscaped retaining wall along the R102 boundary of the site.



Stormwater system being installed as part of the R102 upgrade.



View of the constructed side path along the R102.



Landscaped retaining wall along the R102 boundary of the site.



Landscaped retaining wall along the entrance of the site.



Landscaped retaining wall along the entrance of the site.



Green shade cloth screening that was installed around the perimeter of the mall building.



Laydown area adjacent to the eastern boundary.



Laydown area adjacent to the eastern boundary.



Eastern boundary (N2) retaining wall berm with transplanted indigenous trees.



Eastern boundary (N2) retaining wall berm with transplanted indigenous trees.



Eastern boundary (N2) retaining wall berm with transplanted indigenous trees.



Eastern boundary (N2) retaining wall berm with transplanted indigenous trees.



Delivery refuse yard.